

Сервисный комплект 950 364 506

1


364 208 001




059 5123 09



042 5857 09



2



3

4


364 208 001

059 5123 09




5


042 5857 09




6




7



8



9






Система ABS/EBS Датчик прямой для ротора 80/100 зубьев

Установка и замена датчика



www.haldex.com



www.haldex.com